


Bike	Honda CRF1000L Africa Twin	Part No.	RHA-173-SYS
Year	2015-19	Fit Kits	Z039.10599
Notes	Use standard fittings where not supplied Keep OEM Header Gaskets and Re-use	dB Killer	SCEXDBK24 - (Type W)

Estimated Fitting Time: 90 Minutes



NO.	PART NO.	DESCRIPTION	QTY
1	RSC390	Serket Parallel Silencer	1
2	CP930	L/H Header Pipe	1
3	CP931	R/H Header Pipe	1
4	CP932	Connecting Pipe	1
5	CP933	Connecting Pipe	1
Fit Kit - Z039.10599			
6	Z028.10030	Rubber Coated Spring	2
7	Z016.10002	51-55mm Clamp	1
8	Z016.10003	47-51mm Clamp	1
9	Z026.20068	Alloy Bolt Finisher	1
10	Z026.20049	M8 x 5mm Alloy Spacer	2
11	Z017.10831	M8 x 17mm Washer	2
12	Z017.10044	M8 x 20mm Hex Head Bolt	2
13	Z017.10073	M8 x 25mm Cap Head Bolt	1
14	Z017.12779	25mm Rubber Washer	1
15	Z015.31308	Mounting Bracket	1
16	Z017.10050	M8 x 35mm Hex Head Bolt	1
17	Z017.10825	M8 x 25mm Washer	1

E-MARK	BSAU 193a 1990/t3
DATE	16/10/2018
ISSUE	02
AUTHORISED	J.Harkin

NOTE: ENSURE SCORPION SYSTEM IS CLEAR OF MOVING PARTS AND ALL ORIGINAL FUNCTIONS WORK CORRECTLY.

Bike	Honda CRF1000L Africa Twin	Part No.	RHA-173-SYS
Year	2015-Current	Fit Kits	Z039.10599
Notes	Where not supplied use original fittings	dB Killer	

Estimated Fitting Time: 90 Minutes



A) Remove original exhaust from bike, taking care to keep all original components in a safe place.

B) Refit Scorpion exhaust as per line diagram above.

C) When fitted take bike for a short ride to ensure all functions are correct.

D) When bike & exhaust are cool enough check all nuts and bolts are still secure.

Thank you for purchasing your Scorpion Silencer.

Care of your exhaust: Please refrain from cleaning silencer with heavy solvents or abrasives!

Vielen Dank Für den kauf eines Scorpion Schalldampfers! Pflegehinweis: Bitte verwenden Sie niemals Scheuermittel oder aggressive Reiniger zur Pflege Ihres Auspuffes!

Merci d'avoir choisi un echappement Scorpion.

Entretien de votre silencieux: Ne pas utiliser de solvants ou de produits abrasifs!

Muchas gracias por adquirir un Silencioso Scorpion. Le recomendamos no limpiar el silencioso con productos abrasivos o aquellos que contengan disolventes.



STAY CONNECTED TO RED POWER.