


BIKE	HONDA CBR 600 F	PART NO.	RHA-153
YEAR	2011 - 2016	FIT KITS	Z039.20426
NOTES	Use standard fittings where not supplied <b>Remove standard gasket if fitted.</b>	DB-Killer	SCEXDBK24 - (Type W)



- |   |                                       |
|---|---------------------------------------|
| 1 Conical Serket Silencer RSC197        | 8 2 x M8x17mm Washers (Z017.10831)    |
| 2 2 off Red Power Springs (Z028.10030)  | 9 M8x25mm Cap Head Bolt (Z017.10072)  |
| 3 Connecting Pipe CP635                 | 10 M8x50mm Cap Head Bolt (Z017.10078) |
| 4 43-47mm Band Clamp (Z016.10008)       |                                       |
| 5 Mounting Bracket (Z015.30936)         |                                       |
| 6 2 x Alloy Bolt Finishers (Z026.20068) |                                       |
| 7 2 x M8 Nyloc Nuts (Z017.10062)        |                                       |

E-MARK	SCDB-OS [e4] 2072
ISSUE NO.	04
DATE	15/10/2018
AUTHORISED	J.Harkin
CHECKED	

**NOTE:** ENSURE SCORPION SYSTEM IS CLEAR OF MOVING PARTS AND ALL ORIGINAL FUNCTIONS WORK CORRECTLY.



A) Remove original exhaust from bike, taking care to keep all original components in a safe place.

B) Refit Scorpion exhaust as per line diagram above.

C) When fitted take bike for a short ride to ensure all functions are correct.

D) When bike & exhaust are cool enough check all nuts and bolts are still secure.

Cleaning instruction overleaf:

Box: PLOCK 1

BIKE	HONDA CBR 250	PART NO.	RHA-153
YEAR	2011 - 2016	FIT KITS	Z039.20426
NOTES		FEATURES	

Thank you for purchasing your Scorpion Silencer.

Care of your exhaust: Please refrain from cleaning silencer with heavy solvents or abrasives!

Vielen Dank Für den kauf eines Scorpion Schalldampfers! Pflegehinweis: Bitte verwenden Sie niemals Scheuermittel oder aggressive Reiniger zur Pflege Ihres Auspuffes!

Merci d'avoir choisi un echappement Scorpion.

Entretien de votre silencieux: Ne pas utiliser de solvants ou de produits abrasifs!

"Muchas gracias por adquirir un Silencioso Scorpion. Le recomendamos no limpiar el silencioso con productos abrasivos o aquellos que contengan disolventes."